

VEHICLE INSPECTION REPORT

KU13KWO

Daf LF 55.220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/03/2013

Year 2013

Mileage 590,598 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAE55GF0L421852

Body Style Curtainside

MOT Due 31/07/2026

Cab Type DAY CAB

Tail Lift Cantilever

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Rusted
Over 5mm



3: Grille Front
Scratched (Painted)
UpTo 25mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Cracked
Replace



7: Door Mirror Assy nsf
Missing
Replace



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Door Mirror Assy osf
Missing
Replace



16: Other
N/A
N/A



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Door osf
Chipped
Edge Chip



19: Other
N/A
N/A



20: Seat Base Cover osf
Holed
Over 3mm



21: Seat Base Cover osf
Burn
Over 3mm



22: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK		Service indicator light illuminated	OK	