

# VEHICLE INSPECTION REPORT

**NU69XTS**

## Ford Fiesta 1.5 TDCI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 19/12/2019

Year 2019

Mileage 69,619 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0GXXGAHGKU78119

Body Style Car Derived Van

MOT Due 15/11/2025

CAP Clean £4,675.00

CAP Average £4,125.00

CAP Below £3,300.00

Gearbox MANUAL

Gears 6

\*OUTSTANDING RECALL\* E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Dented  
With Paint Damage



3: Qtr Panel osr  
 Scratched  
 Over 25mm Thru Paint



4: Seat Base Cover osf  
 Soiled  
 Heavy

Interior

|                         |  |      |                             |  |    |
|-------------------------|--|------|-----------------------------|--|----|
| <b>Carpet Condition</b> |  | OK   | <b>Upholstery Condition</b> |  | OK |
| <b>Seat Condition</b>   |  | Poor | <b>Odour</b>                |  | No |
| Engine Runs             |  | OK   | No Excessive Smoking        |  | OK |
| EML light illuminated   |  | OK   | DPF light illuminated       |  | OK |
| ABS light illuminated   |  | OK   |                             |  |    |