

VEHICLE INSPECTION REPORT

PE64EYF

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	03/09/2014	VIN	XLRAEL1500L438059	Gearbox	MANUAL
Year	2014	Body Style	Box Van	Axle Combi	4x2
Mileage	802,064 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout	Tail Lift	Cantilever
GVW	7500kg	MOT Due	30/11/2026		
Colour	RED	Cab Type	DAY CAB		

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door osf
Chipped
Multiple Chips




3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: A Post os
Dented
With Paint Damage



8: Door osf
Chipped
Multiple Chips





9: Door osf
Dented
With Paint Damage

10: Carpets Front
Holed
Over 3mm



11: Door Pad osf
Soiled
Heavy

12: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		